

	<b>National Aeronautical Laboratory</b>	<b>Documentation Sheet</b>	<b>Document Classification</b>  Restricted
<b>Title</b>	:Failure of Dowel Bolts in the Bevel Gear Assembly of an Aeroengine		<b>Document No.</b>  PD MT 8803  <b>Date of issue:</b> Jan 1988
<b>Author(s)</b>	:A.C. Raghuram, S. Radhakrishnan, R.V. Krishnan and V. Ramachandran		<b>Contents</b>  3 pages + 9 figures
<b>Division</b>	:Materials Science		<b>No. of copies:</b> 12
<b>External participation</b>			<b>NAL Project No.</b>  MT-9-871, MT-1-167
<b>Sponsor</b>			<b>Sponsor's Project No.</b>
<b>Approval</b>	:A.C. Raghuram		
<b>Remarks</b>	:		
<b>Keywords</b>	:Aeroengine, bevel gear assembly, spur gear, dowel bolts, nickel-chromium-molybdenum steel, accessory gear box, hydrogen embrittlement		
<b>Abstract</b>	:A set of six dowel bolts made of a nickel-chromium-molybdenum steel, holding together a bevel gear and a spur gear in an aero-engine, failed in service. This led to the separation of the two gears and disruption of drive to the various accessories of the engine, resulting in an accident. Failure analysis revealed that the bolts had failed by hydrogen embrittlement, the hydrogen pick up occurring during the phosphating treatment.		