

 <b>National Aeronautical Laboratory</b>	<b>Documentation Sheet</b>	<b>Document Classification</b> Restricted
<b>Title</b> : FAILURE ANALYSIS OF COMPONENTS FROM THE TAILPLANE ATTACHMENT AREA OF AN AIRCRAFT	<b>Document No.</b> PD MT 8928  <b>Date of issue:</b> July 1989	
<b>Author(s)</b> : A.C.Raghuram, R.V.Krishnan, R.Rangaraju, M.A.Venkataswamy	<b>Contents</b> 3 pages 7 figures	
<b>Division</b> : Materials Science	<b>No. of copies:</b> 10	
<b>External participation</b> : --	<b>NAL Project No.</b> MT-9-001	
<b>Sponsor</b> : --	<b>Sponsor's Project No.</b>	
<b>Approval</b> : Dr A.C.Raghuram		
<b>Remarks</b> : <span style="float: right;">26</span>		
<b>Keywords</b> : Tailplane, Elevator, Rudder		
<b>Abstract</b> : This is an analysis of the cause of fractures of the tailplane components of an HT-2 aircraft. This analysis is done at the request of CRE (aircraft).		