


**National
Aeronautical Documentation Sheet
Laboratory**

Document Classification

Restricted

Title : Analysis of cracking of HP Turbine
Blades of an Aeroengine

Document No.

PD MT 8933

Date of issue: Nov.89

Author(s) : A.C.Raghuram, R.V.Krishnan,
R.Rangaraju and M.A.Venkataswamy

Contents

5 pages
7 figures

Division : Materials Science

No. of copies: 10

External participation :

NAL Project No.

MT-9-001

Sponsor :

Sponsor's Project No.

Approval : A.C.Raghuram

26

Remarks :

Keywords : H.P.Turbine blade, Cracking, Thermal Fatigue

Abstract : A detailed examination of the cracking of aeroengine HP turbine blades has been carried out to determine the cause of cracking. Investigations point to design deficiency at the leading edge, particularly with regard to the orientation of the film cooling holes, as the most probable cause of failure.